

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE:** 10/05/01

**CORNER DESIGNATION:** 2N32Z13, The Northeast Corner of Section 4.

**PREVIOUS RENEWALS/ SURVEYS, ETC..:**

Most recent Umatilla County Surveyors Corner Record: 93-109-C

**MONUMENT AND ACCESSORIES FOUND:**

Found 2 1/2" brass cap on galvanized iron pipe monument with cap 2" above ground level in good condition, marked as shown in monument marking detail.

Per corner record, all accessories are intact except steel fence post with witness post sign is gone from accessory located to the Southwest.

**MONUMENT MARKING DETAIL:**

T2N R32E  
S33 | S34  
S4 | S3  
T1N R32E  
1994  
PLS 1106

**LOCATION & COMMENTS:**

Corner falls in between Southwest edge of County Road #1331 and the right-of-way fence approximately 2.5 feet Northerly of fence.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 710138.33  
E = 8635281.21

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N32Z13

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

RECEIVED BY

Umatilla County Surveyors

Date 2-02

Received By RK

No. 02-44-9