


Index  
File No. L-9

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_ Cor.  
No. \_\_\_\_\_T 3S R. 33E R.D. Ukiah County \_\_\_\_\_Merid. Will. N.F. Umatilla State Oregon

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

None could be found.

2  
DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND - A 16" DBH Ponderosa pine bearing N 47 degrees E 10 links is slightly on the SW. exposed ridge. Very steep here. There is an old fence bearing N & S. The wire on the fence is smooth no barbs. No other evidence could be found of the corner.  $\frac{1}{4}$ S can be seen & is in good condition. I painted scars & scribing & painted a six inch red band around the tree. Attached a bearing tree tag on scribing side of tree with an attention sign on the back.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By Tags & Paint*Signature*

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

4  
Signature MLC & DDH Title Forestry Tech. Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date 10/3/79 7100-52-(3/68)  
5

**CORNER RECORD (PERPETUATION)**

**MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

**ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

**REMARKS**

Index File No. T. R. M. Tract or Surv. No. Cor.