

AGENDA ITEM FOR ADMINISTRATIVE MEETING

() Discussion only
() Action

FROM (DEPT/ DIVISION): UCSO/Criminal

PROGRAM: 1560

SUBJECT: Vehicle Repair

<p>Background: Vehicle 21-05 was damaged during a vehicle pursuit on 1/28/2023. We received initial estimates from body repair shops, and Zimmerman’s in Athena was chosen to conduct the repair. The estimate at that time was under \$5000, so authorization to proceed was obtained from the County CFO.</p> <p>On 3/9/2023 we received information from Zimmerman’s that additional damage was discovered upon starting the repair. The new estimate for total cost is \$5535.65.</p> <p>Zimmerman’s has most of the parts in stock already and can begin repair immediately upon approval. This vehicle is needed in the fleet, thus its return to service is a priority.</p>	<p>() <u>ACTION REQUESTED:</u> Approve Zimmerman’s Auto Body to continue with repairs for an estimated cost of \$5535.65.</p>
--	---

ATTACHMENTS: Estimate

Date: () Submitted By: (Josh Roberts)

*****For Internal Use Only*****

Checkoffs:

- () Exec. Asst.
- () Dept. Head (copy)
- () Human Resources (copy)
- () Budget (copy)
- () Fiscal
- () Legal (copy)
- () (Other - List:)


To be notified of Meeting:
Undersheriff Jim Littlefield
Captain Paul Wolverton
Lieutenant Josh Roberts

Needed at Meeting:
Captain Paul Wolverton
Lieutenant Josh Roberts

Scheduled for meeting on: March 15, 2023

Action taken:

Follow-up:



Date: 3/ 9/2023 01:4
 Estimate ID: 98
 Estimate Version: 0
 Preliminary
 Profile ID: Mitchell

IF YOU ARE SENDING THE INSURANCE CHECK TO OUR FACILITY PLEASE MAIL IT TO:

ZIMMERMANS AUTOBODY & GLASS D.B.A ADAPT AUTO REPAIR LLC
 PO BOX 783
 ATHENA, OR 97813

ZIMMERMAN'S AUTO BODY & GLASS D.B.A ADAPT AUTO REPAIR LLC

PO BOX 783 , ATHENA , OR 97813
 (541) 566-0120
 Email: ZIMMS.ADAPTREPAIR@GMAIL.COM

Damage Assessed By: daniel caswell
 Classification: Audit

Deductible: UNKNOWN

Insured: UMATILLA COUNT SERRIFF
 Owner: UMATILLA COUNTY SHERIFF
 Address: PENDLETON, OR 97801
 Telephone: Home Phone: (541) 969-1771

Mitchell Service: 911653

Description: 2021 Dodge Durango SXT
 Body Style: 4D Ut Drive Train: 3.6L Inj 6 Cyl AWD
 VIN: 1C4RDJFG9MC643022 License: 21-05
 OEM/ALT: O Search Code: None
 Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, REAR WINDOW DEFOGGER
 AIR CONDITION, REAR WINDOW WIPER, CRUISE CONTROL, TILT STEERING COLUMN
 AM/FM STEREO, DRIVER AIRBAG, HEATED EXTERIOR MIRROR, REAR (DUAL-ZONE) AC
 FRONT SIDE AIRBAG WITH HEAD PROTECTION, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
 FOG LIGHTS, ALUM/ALLOY WHEELS, REARVIEW CAMERA, TIRE INFLATION/PRESSURE MONITOR
 AUXILIARY INPUT, BLUETOOTH WIRELESS CONNECTIVITY, LEATHER STEERING WHEEL
 SATELLITE RADIO, POWER ADJUSTABLE EXTERIOR MIRROR, 4WD OR AWD, PRIVACY GLASS
 AUTO AIR CONDITION, TRIP COMPUTER, FIRST ROW BUCKET SEAT
 REAR HEATING, VENTILATION & AIR CONDITIONING, CLOTH SEAT, ALL WHEEL DRIVE
 SIDE AIRBAGS, AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION
 INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR, MP3 PLAYER
 DAYTIME RUNNING LIGHTS, ELECTRONIC STABILITY CONTROL, KEYLESS ENTRY SYSTEM
 REAR BENCH SEAT, REAR SPOILER, SMART KEY SYSTEM, STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	101786	BDY	REMOVE/INSTALL	Frnt Bumper Cover			INC #
2	AUTO	BDY	OVERHAUL	Frnt Bumper Cover Assy			4.6 #
3	104494	BDY	REMOVE/REPLACE	Frnt Bumper Cover	68510292AD	522.00	INC #
4	AUTO	REF	REFINISH	Frnt Bumper Cover			C 3.2
5	104419	BDY	REMOVE/REPLACE	R Frnt Bumper Cover Grille	6UZ32RXFAA	9.35	INC
6	104432	BDY	REMOVE/REPLACE	L Frnt Bumper Cover Grille	6UZ33RXFAA	9.35	INC
7	100857	BDY	REMOVE/INSTALL	R Front Combination Lamp			0.6 #
8	AUTO	BDY	REMOVE/INSTALL	Grille Assy			0.4 #
9	100835	BDY	REMOVE/INSTALL	L Front Combination Lamp			0.6 #
10	101809	BDY	REMOVE/REPLACE	Hood Panel (Alum)	55369453AF	890.00	1.7
11	AUTO	REF	REFINISH	Hood Outside			C 2.9
12	AUTO	REF	REFINISH	Add For Hood Underside			C 1.4

ESTIMATE RECALL NUMBER: 03/09/2023 13:44:35 98
 Mitchell Data Version: OEM: FEB_23_V



Date: 3/ 9/2023 01:4
 Estimate ID: 98
 Estimate Version: 0
 Preliminary
 Profile ID: Mitchell

13	100J02	REF	BLEND	R Fender Outside					C 0.8
14	100811	REF	BLEND	L Fender Outside					C 0.8
15	100812	REF	BLEND	R Add To Edge Fender					C 0.2
16	100813	REF	BLEND	L Add To Edge Fender					C 0.2
17	104006	BDY	REMOVE/REPLACE	R Fender Liner	68504092AA		75.45	0.4	
18	900500	FRM *	REPAIR	RACK LABOR	Existing			2.5*	
19	100818	BDY	REMOVE/INSTALL	R Fender Wheel Opening Mldg					INC #
20	100819	BDY	REMOVE/INSTALL	L Fender Wheel Opening Mldg					INC #
21	100820	BDY	REMOVE/INSTALL	R Fender Splash Guard				0.2	
22	100821	BDY	REMOVE/INSTALL	L Fender Splash Guard				0.2	
23	100602	BDY	REMOVE/REPLACE	L Fender Wheel Opening Mldg	57010621AF		202.00		INC #
24	100603	BDY	REMOVE/REPLACE	R Fender Pin 10@9.95	6508863AA		99.50		
25	100243	BDY	REMOVE/INSTALL	R Rocker Moulding				0.8	
26	100244	BDY	REMOVE/INSTALL	L Rocker Moulding				0.8	
27	100373	BDY	REPAIR	R Frt Door Shell	Existing			3.5* #	
28	AUTO	REF	REFINISH	R Frt Door Outside					C 2.2
29	101713	BDY	REMOVE/INSTALL	R Frt Rear View Mirror				0.3 #	
30	101717	BDY	REMOVE/INSTALL	R Frt Otr Door Belt Moulding				0.4	
31	101694	BDY	REMOVE/INSTALL	R Frt Door Trim Panel					INC
32	101690	BDY	REMOVE/INSTALL	R Frt Otr Door Handle				0.3 #	
33	AUTO	BDY	REMOVE/INSTALL	R Frt Door Carrier				1.8 #	
34	104057	BDY	REPAIR	R Rear Door Shell	Existing			4.0* #	
35	AUTO	REF	REFINISH	R Rear Door Outside					C 1.9
36	101744	BDY	REMOVE/INSTALL	R Rear Otr Door Belt Moulding				0.4	
37	102679	BDY	REMOVE/REPLACE	R Rear Door Protector	68088806AA		61.70	0.2 #	
38	101033	BDY	REMOVE/INSTALL	R Rear Door Trim Panel				0.4	
39	101732	BDY	REMOVE/INSTALL	R Rear Upr Door Trim				0.2 #	
40	101742	BDY	REMOVE/INSTALL	R Rear Otr Door Handle				0.3 #	
41	101186	BDY	REMOVE/REPLACE	R Quarter Wheel Opening Mldg	57010618AH		222.00	0.4	
42	101184	BDY	REMOVE/REPLACE	R Quarter Rivet 4@9.35	6500911		37.40		
43	AUTO	REF	ADD'L OPR	Clear Coat					3.6
44	AUTO		ADD'L COST	Paint/Materials			688.00	*	
45	AUTO		ADD'L COST	Shop Materials			40.00	*	
46	AUTO		ADD'L COST	Hazardous Waste Disposal			5.00	*	

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc


Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	22.5	62.00	0.00	0.00	1,395.00 T	Taxable Parts	2,128.75
Refinish	17.2	62.00	0.00	0.00	1,066.40 T		
Frame	2.5	85.00	0.00	0.00	212.50 T	Total Replacement Parts Amount	2,128.75
					Taxable Labor		2,673.90
Labor Summary	42.2						2,673.90

ESTIMATE RECALL NUMBER: 03/09/2023 13:44:35 98
 Mitchell Data Version: OEM: FEB_23_V

Software Version: 7.1.242

Copyright (C) 1994 - 2023 Mitchell International
 All Rights Reserved



Date: 3/ 9/2023 01:44 AM
 Estimate ID: 98
 Estimate Version: 0
 Preliminary
 Profile ID: Mitchell

III. Additional Costs	Amount	IV. Adjustments	Amount
Taxable Costs	733.00	Customer Responsibility	0.00
Total Additional Costs	733.00		
Paint Material Method: Rates			
Init Rate = 40.00 , Init Max Hours = 99.9, Addl Rate = 0.00			
		I. Total Labor:	2,673.90
		II. Total Replacement Parts:	2,128.75
		III. Total Additional Costs:	733.00
		Gross Total:	5,535.65
		IV. Total Adjustments:	0.00
		Net Total:	5,535.65

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.