



WELL NO. 1:
 N. 57° 42' W.
 449.3'

WELL NO. 2:
 N. 60° 31' 10" W.
 435.7'

I, Wayne O. Harris, Registered Oregon Land Surveyor, No. 346, do hereby certify that this map was made from notes taken during an actual survey made by me on the 19th day of September, 1955; that the plat as shown is a correct representation thereof.

Wayne O. Harris
 Dep. County Surveyor

REGISTERED
 OREGON
 LAND SURVEYOR

Wayne O. Harris

MAY 6, 1953
 WAYNE O. HARRIS
 346

HAYES & HARRIS ENGINEERING		
SURVEY FOR FRANK DUFF		
WELL LOCATIONS AND WATER RIGHT SECTION 27, T. 3 N., R. 33 E., W.M.		
SCALE 1" = 300'	DATE 9-21-55	DRAWN BY W.O.H.

257-9-55