



NOTE: Bearings are based on the line between the NW Corner of Sec. 22 and the SW Corner of Section 34 being Due South.

Restablishment by Proportionate Method

Set Brass Cap (Umatilla County Surveyor, 1971)

REGISTERED
OREGON
LAND SURVEYOR

Ralph P. Thompson
MAY 13, 1960
RALPH P. THOMPSON
506

SURVEY FOR
UMATILLA COUNTY ROAD DEPT.
REESTABLISHMENT OF THE
SOUTHWEST CORNER
Sec. 27, T.5N.R.29 EWM

Date: 5-5-71 | Scale: 1"=2000'

RALPH THOMPSON
REGISTERED LAND SURVEYOR
P. O. BOX 1082 PENDLETON, ORE. 97801