

OREGON CORNER RESTORATION FORM

Section 25 Township 1 N Range 32 EWM
County Umatilla Date 10 October 2004

V-25

CORNER DESIGNATION

Southeast Corner

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

David P. Thompson, Contract 106, August 16, 1864
Zenas F. Moody, Contract 164, October 4, 1871

Monument(s) & Accessories Found: (Condition and Source)

Fence Line West and South, Plow line East

Thompson set posts and dug pits, Moody did the same

Monument Detail

Sketch



2 1/2" BRASS CAP
ON 1 1/2" X 30"
IRON PIPE

Monument Set (Procedures and Description)

Set Brass Cap at Fence Intersection
Set 5/8" X 30" Iron Rebar w/ Alum. Cap stamped PLS 933
15 Feet North East, South and West

New Accessories

Location sign on Fence Post 1 foot South

Location & Comments

The West line of the Section is 1 1/2 miles South of Spring Cr. RD.
Compass Declination _____
Firm/Agency Krumbein Engineering
Address 361 S.E. 2nd Pendleton, OR. 97801
Party Chief David Krumbein
Notes _____
Witness _____

Surveyor's Seal

