

CERTIFICATE OF REMONUMENTATION

July 2, 2003

I, William R. Wells, Professional Land Surveyor in the State of Oregon, do hereby state that I have reestablished or recovered the following Lot Corners in the Southeast Quarter of Section 2, T2N., R32E., W.M., City of Pendleton, Umatilla County, Oregon.

The previously existing monuments of record have been covered with earth fill or destroyed during construction of NW Johns Lane improvements in the spring of 2003.

The reestablished or recovered monuments have previously been tied or established by me on Survey No. 01-152-C or the Plat of North Main Addition, recorded at Book 14, Page 16, Record of Town Plats, Umatilla County Office of Records.

Reestablished corners are monumented with 5/8 inch by 30 inch iron rebars with 1 1/4 inch yellow plastic caps marked "OR PLS 1106 WA PLS 17372": Corner monuments recovered are noted.

The reestablished or recovered monuments are:

IN FIRST ADDITION TO STANGIER HILLS, BLOCK 3:

Recovered a 1/2 inch iron rebar at correct position at the Northwest Corner of Lot 8, and reestablished the Northerly Lot Corner common to Lots 7 and 8. Reestablished the beginning of curve monument on the North line of Lot 7, the Northerly Corner common to Lots 7 and 6 and the Northeast Corner of Lot 6. The monuments reestablished show on Survey No. 01-152-C.

IN NORTH MAIN ADDITION:

Reestablished the Northwest Corner of Lot 4, the beginning of curve point on the North line of Lot 4 and the Northerly Lot Corner common to Lots 4 and 5. Reestablished the Northerly Lot Corner common to Lots 5 and 6, the two monuments on the tangent (3.52 feet apart) on the North line of Lot 6 and the point of curvature and point of tangency at the ends of Curve 8 on the Northerly line of Lot 6. Reestablished the monument at the intersection of the East right-of-way line of North Main Street and the South line of NW Johns Lane. The 2 inch brass cap set in concrete at the intersection of the centerline of North Main Street and the South Line of NW Johns Lane is still in place, but covered by new asphalt paving. The reestablished monuments show on the Plat of North Main Addition.

Dated this 2nd day of July, 2003.

William R. Wells
William R. Wells, PLS 1106
P.O. Box 1696
2602 NE Riverside Place
Pendleton, Oregon
Phone: (541) 276-6362

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-04

RECEIVED BY
Umatilla County Surveyor
Date 7-03
Rec'd By SR
No. 03-127-R