

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 9/19/01

CORNER DESIGNATION: 2N32, V-19, South 1/4 Corner of Section 26.

PREVIOUS RENEWALS/ SURVEYS, ETC...:

Most recent is Umatilla County Surveyor's Corner Record No. 94-109-C.

MONUMENT AND ACCESSORIES FOUND:

Found 2 1/2" brass cap on 1 1/4" x 30" galvanized iron pipe, cap buried 12" below ground, marked as shown in monument marking detail, in good condition. As per Corner Record, all accessories exist although steel fence post with witness post sign for accessory positioned at S 38° E, 21.7 feet is gone. Corner has four accessories.

MONUMENT MARKING DETAIL:

T2N R32E
1/4 S26
S35
1994
PLS 1106

LOCATION & COMMENTS:

Corner falls in non-farmed pasture approximately 130 feet South of centerline of Tutuilla Road.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 715558.60
E = 8643107.72

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N32V19

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Will. R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By KR

No. 01-210-9