

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 11/15/01**

**CORNER DESIGNATION: 2N33, V-1, The Southwest Corner of Section 30 only.**

**PREVIOUS RENEWALS/ SURVEYS, ETC..:**

Corner point was monumented by BLM in 1988 Dependent Resurvey recorded in the Umatilla County Surveyor's Office.

**MONUMENT AND ACCESSORIES FOUND:**

At corner point, found a 3" brass cap on stainless steel monument a monument box, 8" below road surface, marked as shown in monument marking detail. There is a witness corner monument 30.03 feet East of true corner monument marked:

WC  
WEST  
30.03'  
R32E T2N R33E  
S25|S30 CC  
|S31  
1982  
PLS 1106

**MONUMENT MARKING DETAIL:**

U.S. DEPT. OF THE INTERIOR  
U.S. BUR. OF LAND MANAGEMENT  
T2N  
R32E|R33E  
S25|S30 CC  
|S31  
1988

**LOCATION & COMMENTS:**

Corner located in gravel approximately 40 feet North of intersection of Goad Road and Lloyd Road.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 715758.34  
E = 8651023.34

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N33V1

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Will R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By KR

No. 01-211-9