## OREGON CL NEW RESTORATION FLAM Township Section 05.06 4N Range 31E County Umatilla Date: 05-08-2006 Corner Designation: 4N31E A5 Condition Report Only Not Found Remonumented Unrecorded Surveyed In Previous Renewals / Surveys, etc. Referenced Out (110) "Set post Standard corner for Sec 08-1865 W.Odell/Lewis STD PARALLEL 08-1865 W.Odell/Lewis STD PARALLEL (110) "Set post Standard corner for Sec 31 & 32. Drove charred Stake and Raised Mound with pits as per instructions." 01-1867 W.Odell GLO Subdv (114) "Intersected 1st Standard parallel North 77 links West of Post Standard corner for sections 31 & 32 T5N R31E, At point of intersection set Closing corner for sections 5 + 6 drove charred stake dug pits, and raised mound as per instructions." ---SUBDIVISION OF T4NR31E---12-1874 N.Walden Resurvey (209) "A point-23 lks. West-and 86 lks.North of the corner to Secs.31 + 32" 05-1974 D.Krumbein (I-25-B) "FND FENCE COR SET BRASS CAP" 06-1974 D.Krumbein (I-24-B) "FND FENCE COR SET BRASS CAP" 06-1974 D.Krumbein (I-167-B) "FND FENCE COR SET BRASS CAP" 05-1980 W.Kimmel BLM (83-195-B) "...monumented with an iron post, 2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd." diam., firmly set, projecting 6 ins. above ground, with brass cap mkd. Monument and Accessories Found: (condition and source) Found 2-3/8 dia Brass Capped monument on a 2" dia Iron pipe 2 ins. above ground and leaning $15\,^\circ$ South. RM 4 South Cold DIAGRAM 5' Steel T-Post SURVEYOR COUNTY 5 ft steel T-Post with a Umatilla County Survey T5NR31E HIGHWAY seci RM 3 6 S75 •48 'E sec 31 30 287.0ft UMA South Cold Springs Highway centerline 5 6 RM 2 S89 \*39 E 256.1ft 6 sec sec TRM 1 5/8"dia. x 24" long Iron Rebar with a 1.3"dia. Red Plastic cap. T4NR31E Burned. N88 \*29 'W ALS 62 Fnd 2-3/8 dia. Brass cap on a 2.00 OD Galvanized 2.5ft pipe monument. MONUMENT(S) AND ACCESSORIES SET (Procedures and Description) Set a 5' T-Post East of RM1 with a Bearing Object sign at the base. Set a 5 ft steel T-Post with a Umatilla County Survey Marker sign facing SouthWest toward South Cold Springs highway. REFERENCES SET: Set four (5/8" dia x 24" long Iron rebar with a 1.3" dia. Red Plastic cap) to the bearings and distances from monument shown above in the sketch. Made GPS tie to TRI Stations LAURILA RESET RB 1379 and Oregon State Plane Coord. - North Zone 804539.15 Northing WALLS RB 1396 Easting 8590701.61 45 °51 '48.026317"N 118 °58 '28.393908"W Latitude Ortho Height 1166.29 Longitude Ellipsoidal Height 1028.40 NAD 83 (1991) Compass Declination Location and Comments 18 °E Surveyors Seal Proceed from the Jct of Hwy 37 and South Cold Sprnigs Highway 2.00 miles South East on South Cold Springs Highway. Corner is North of the Highway 275 feet up the plowed field. Mile-post 23-1/4. REGISTERED PROFESSIONAL LAND SURVEYOR David L. Haddork RECEIVED BY: Firm / Agency OREGON JULY 12, 1968 DAVID L. HADDOCK Date: 05-06 Haddock Surveying Rec'd By: P. O. Box 1574 Pendleton, OR 97801 06-263-C 852

(541) 276-2174

RENEWS 6-30-07