

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 5S R. 33E Will. Mer.

Section Corner common to Sections

1, 2, 11, and 12

Corner consists of a Rock Mound (not) in place
State condition Fair

Dimensions above ground 6 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

TSS
R33
Sec 1

TSS
R33E
Sec 2

TSS
R33E
S 12

--

BT

BT

BT

--

Species	<u>WL</u>	<u>WLS1149</u>	<u>LP</u>
Diameter	<u>24"</u>	<u>18"</u>	<u>10"</u>
Bearing	<u>N61°E</u>	<u>N73°W</u>	<u>S32°E</u>
Distance	<u>52 LKS</u>	<u>51 LKS</u>	<u>42 LKS</u>

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

G. J. Warren

(Signature)

Forest T.M.

(Title)

1/7/53
(Date)

T. _____ R. _____ Mer.

(Make sketch of topography near Corner and show section line markers thus "X")

Sec.		Sec.	
Sec.		Sec.	

Metal Location Poster is on a _____

tree _____ inches diameter, on the _____

side of _____ from which

this Corner bears _____ Chains.

(Bearing) (Distance)

Section line marker between Secs. _____ and _____ is on

a _____ on the _____

(Tree, post, etc.)

(Name of road, trail, etc.)

located _____ chains E, W, N, S, from Sec. Cor.; $\frac{1}{4}$ Cor.; Witness Cor.

(Cross out nonapplicable)

Give any further facts needed to find Corner again:

USDA-FOREST SERVICE

Index
File No. E-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____


T 58 R. 33E

R.D. Ukiah County Umatilla

Merid. W.M.

N.F. Umatilla State Or.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

2 1/2" iron pipe with brass cap mkd:

T58 R33E
S2 | S1
S11 | S12
1977

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

D. fir, 10", N31°W, 2.8 ft.
Tamarack, 23", N81°E, 35.3 ft.
D. fir, 13", S57 1/2°E, 33.5 ft.
Uprooted & badly rotted pine stump bears S14°W.
14.3 ft.
Tamarack stump, 17", N73 1/2°W, 34.4 ft.
(continued in "Remarks")

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor. falls on N. slope approx. 500' N. of powerline.

Signature
F. L. Munro

Title
L.S.

Division

Headquarters

Date
9/13/84

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BTs have reqd. paint, tags & signs.

Work Done By F.S. Munro Title L.S. Date 9/13/84 State Registration No. 1832
for Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

D. fir, 10", S18 $\frac{1}{2}$ °W, 36.2 ft.
Uprooted Lodgepole, 13", root hole bears S36°E, 28.2 ft.

Index File No. E-2/ T. 5S R. 33E M. W.M. Tract or Surv. No. _____ Cor. _____