

GOVERNMENT CORNER RECORD

Township 6N Range 35E Section 35 County UMATILLA

State OREGON Date 10/1/96 Number Y-20

Corner Designation : SE 1/16 CORNER SECTION 35

- Condition Report Only
- Not Found
- Renewed
- Surveyed In
- Referenced

Previous Renewals _____

Monument (s) Found: (Condition and Source)

FOUND RAILROAD SPIKE .05' UNDER PAVEMENT.

MONUMENT DETAIL

Found Set

Accessories Found:

NONE

NO SKETCH AVAILABLE

Monument & Accessories Set (Procedure and Description)

SET P.K. NAIL AND ALUMINUM TAG IN POWER POLES 17.92' N.W. AND 55.15' N.E.

TIED TO CONCRETE DRIVEWAY CORNERS 26.32' AND 39.43' S.W.

(SEE SKETCH DETAIL BELOW)

<p style="text-align: center;">Sketch of Monument, Accessories and General Area</p>	<p style="text-align: center;">Surveyor's Seal</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>REGISTERED PROFESSIONAL LAND SURVEYOR</p> <p><i>Danny K. Cummings</i> 10/3/96</p> </div> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>OREGON JAN. 21, 1988 DANNY K. CUMMINGS 2316</p> </div> <p>RENEWAL DATE : 12-31-97</p> <p style="text-align: center;">GASCHLER & CUMMINGS</p> <p>Agency _____</p> <p>Party Chief <u>D. CUMMINGS</u></p> <p>Notekeeper <u>L. KING</u></p> <p>Witness(s) _____</p> <p>Field Book #0-135 pg10-11</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>COUNTY SURVEYOR RECORDING INFO</p> </div> <p>Received _____</p> <p>Filed _____</p> <p>Survey No. <u>96-164-B</u></p> <p>Drawing No. _____</p> <p>Index No. _____</p>
--	---