

Chains	<p>I run S.00° 38' W. on a true line between Secs. 5 &amp; 6.</p> <p style="text-align: center;">Var.</p> <p>38.70 Set Fir post on S. slope for <math>\frac{1}{4}</math> Sec. Cor. A Tamarack, 12 ins. in diam., bears N.78°E., 17 lks. dist. " " 18 " " " " N.84°W., 13 " "</p> <p>70.70 Leave timber, E.&amp;W.</p> <p>78.70 The Cor. to Secs. 5, 6, 7 &amp; 8.</p> <p>Land; Surface rolling plateau. Soil; 2nd &amp; 3rd rate. Heavy timber, Tamarack, Fir, Spruce and Pine. Some Willow and Alder underbrush.</p> <p style="text-align: right;">Oct. 27, 1879.</p>	-100
	<p>General Description</p> <p>Surface is mountainous; N. row of Sections, rolling plateau teau. Soil mostly 3rd rate, some on plateau 2nd rate and small part on Umatilla River 1st rate.</p> <p>The timber on the plateaus and along the water courses is generally heavy and valuable; on the hillsides it is irregular, being either in thick small groves or open and scattering and cannot be indicated on the plat.</p> <p>There are a number of settlers, but their cabins cannot be seen from the lines.</p> <p>Though the surface of this Township is not all covered with timber, yet, the timber there, is, <sup>here</sup> for this very reason, all so much the more valuable.</p>	