

Survey
Meters
Chains
Links

- 39 57 Runce 9 m North bet Nos 29 & 30
- 39 57 He 1/4 Sec cor bet Nos 29 & 30
- Runce 9 m South bet Nos 29 & 30
- 39 97 Set Stone 18 + 12 + 8 in mid of Stone for cor of Nos 29-30-31 & 32
- Thence west on June line
- 39 97 Set Stone 16 + 8 + 7 for 1/4 Sec
- 39 82 He 1/4 Sec cor Thence 9 m
- South through center No 31
- 39 96 June 8 & W line through center No 31
- 39 36 a point 5 m E of 1/4 Sec Cor
- West through center SW 1/4 No 31
- 40 11 He 1/4 Sec cor on W bdy No 31
- Thence East on June line
- 20 05 1/2 Set Stone 16 + 8 + 6 for center SW 1/4 No 31
- West on June line through center W 1/2 No 31
- 20 25 1/2 Set Stone 19 + 8 + 6 in mid of Stone on rocky SW No 31
- for 1/4 Sec cor in center W 1/2 No 31

John W. Kirkell County Surveyor