

Keen & Shick Oct 19 1904 14 N 56 34 6 W

Acres. Poles. Chains. Links.

J. S. King and John Davis Chairman John Keen Flanagan

I commenced at the cor of Sec 3-4-9 810

thence East bet Secs 3 810

39 92 a point - 46 lls South of the $\frac{1}{4}$ Sec cor bet Secs 3 810

50 66 a point - 24 lls N of the cor of Sec 2-3-10 811

thence South bet Secs 10 811

40 20 fence runs East N 8 S

50 28 The cor of Secs 10-11-14 815

thence West bet Secs 10 815

40 00 a point - 100 lls South of corner point for $\frac{1}{4}$ Sec cor bet Secs 10 815
as indicated by Wm Scott and others as original $\frac{1}{4}$ Sec cor

50 20 the cor of Secs 9-10-15 816

thence North bet Secs 9 810

20 00 set survey $\frac{1}{16}$ cor set Stone for $\frac{1}{16}$ cor

40 00 " " $\frac{1}{4}$ Sec cor " Post " $\frac{1}{4}$ Sec cor and Stone

60 50 " " $\frac{1}{16}$ cor " Stone 16 + 8 + 6 for $\frac{1}{16}$ cor

50 00 The cor of Sec 3-4-9 810

East through center Sec 10

40 00 set survey center Sec 10

50 58 a point - 163 lls N of point for $\frac{1}{4}$ Sec cor

North through center Sec 10

17 20 set $\frac{1}{16}$ corner in center $S \frac{1}{2}$ Sec 10

38 50 Iron C & W line bet Stone for $\frac{1}{16}$ cor center Sec 10

59 16 set Stone for center N $\frac{1}{2}$ Sec 10

John W. Kimbell County Surveyor