

By request of J. B. Colver and L. S. Hubbard Jan. 5th 1906

Chains Links

South lot nos 22 and 23

40 00 could find no trace of $\frac{1}{4}$ sec corner

80 00 " " " " of cor to nos 22-23-26 & 27

North lot nos 26 & 27

23 00 ditto N 88 S W

40 00 could find no trace of $\frac{1}{4}$ sec corner

80 00 a point - 65 East of cor to nos 26-27-34 & 35 -

Thence No. 6' E on true line

80 00 set Post 4x4 in 4 ft long for cor to nos 22-23-26 & 27

Thence west lot nos 22 & 27

40 00 set Surveyors $\frac{1}{4}$ sec cor

80 00 a point - 42 lbs South of cor to nos 21-22-27 & 28

S 87 42' E on true line

40 00 set Stone 15x6x4 for $\frac{1}{4}$ sec corner

North lot nos 21 & 22

44 50 ditto ditto N 88 S W 20-40 W type

52 80 Nail Head N 88 S W

80 42 a point - 44 lbs East of cor to nos 21-22-15 & 16

So. 39' E on true line

20 00 set post for the one

40 00 " lot for $\frac{1}{4}$ sec corner

South lot nos 27 & 28

32 25 Nail Head N W 88 E

40 00 set Surveyors $\frac{1}{4}$ sec cor

79 07 the cor to nos 27-28-33 & 34

39 58 North on true line

set post for the one

John W. Simbrell County Surveyor