

by request of H. S. Burns - Wm. Hest and A. A. Hoy out 25 1910

Chains Links

Section 36 T 6 N R 35 E W M

Commencing at NW cor No 36

South 60° 30' 00" East 20.00' to 30.00' the 1st survey 1/4 or

4010 The 1/4 po. corner bet No 35 &amp; 36

Thence north on same line

10 00 1/2 ft stone for corner

20 05 1/2 ft stone for 1/4 corner

East bet No 25 &amp; 36

20 00 1/2 ft survey 1/4 or

40 02 The 1/4 po. corner

East through center bet No 36

80 52 The 1/4 po. cor

East through center of 1/2 of NW 1/4 No 36

20 23 1/2 ft stone for 1/4 cor

North through center bet No 36

80 52 a point 600 yds west of 1/4 po. cor

South on same line

40 26 The center bet No 36

Thence west through center NW 1/4 No 36

20 13 1/2 ft stone for center NW 1/4 No 36

John W. Ambrose County Surveyor

witnessed by A. A. Hoy and Wm. Hest Chain

and H. S. Burns Flagman