

Hall and Hester

April 14 1913

J 2 N 1633 6 Wm

Chains Links

- West Hays cut Sec 26
- 20 -- set Hays  $\frac{1}{16}$  "
- 40 -- " "  $\frac{1}{16}$  " cut Sec 26
- 60 -- " "  $\frac{1}{16}$  " cut  $W \frac{1}{2}$  Sec 26
- 81 20 To top corner set Sec 26 927
- East set Sec 26 933-
- 60 80 To corner Sec 25-26-35 & 36
- West on true line
- 40 40 set Stone 18+8+6 for  $\frac{1}{16}$  sec "
- 60 60 " " 16+8+5 for  $\frac{1}{16}$  sec "
- North Hays cut Sec 26
- 39 96 True 6 94 line set Stone 18+8+6 for cut Sec 26
- True East on true line
- 20 30 set Stone 14+8+5 for  $\frac{1}{16}$  sec cut  $S \frac{1}{2}$  Sec 26
- East set Sec 23 & 26 from  $\frac{1}{16}$  sec "
- 40 17 To corner Sec 23-24-25 & 26
- West on true line
- 20 08 1/2 set Stone 16+8+6 for  $\frac{1}{16}$  sec "
- 70 17 To  $\frac{1}{16}$  sec "

Geary Humboldt County Oregon by John W. Humboldt Survey