

3M-214

3M-216

NZ-3MM-165

82-50
F9

35 34
4 3

34 35
3 2

X 450

X $\frac{D}{754.0}$

297.4

754.0
wht

-D-190-

4
9 10

3 2
10 11

$\frac{A}{181.4}$

D-226
(-H-379-)

3M-164

3M-167

$\frac{E}{75.7}$ X

75.7
wht

$\frac{A}{139.4}$

D-226
(H-74)

wheat

$\frac{L}{165.1}$

wht

-D-190-

-H-257-

9 10
16 15

16 11
15 14

5-22-71

304.37

3M-217