

5M-112  
T5N-R28E

8 9  
17 16

9 10  
16 15

10 11  
15 14

NZ-3MM-328

D-3

A  
31.9  
-E-729-

17 16  
20 21

16 15  
21 22

15 14  
22 23

3M-330

3M-325

A

-E-791-

D  
30.7

H  
34.0

D  
13.3

A  
E-995

B  
21.3

-E-289-

20 21  
29 28

21 22  
28 27

22 23  
27 26

5-22-71

3M-201