

1450 Summit - Descend
 1830 Draw SW - Ascend
 1950 Summit - Descend
 2140 Ravine SW - Ascend
 2400 Summit - Descend
 3225 Gulch SW - Ascend
 3714 Wire fence E. & W.
 4850 Summit - Descend
 5240 Gulch SW - Ascend
 5280 Set 1 m p 25 East of line

350 Wire fence E. & W. NW cor Dec 2
 450 Summit - Descend
 1200 Gulch SW - Ascend
 1720 Leave fence - Enter plowing
 2500 Summit - Descend
 2982 Cor fences N. & S. W.
 4300 Gulch S.E. Ascend
 5000 Summit

North

5280 Set 2 m p 25 E of line

353 Stone cor = SW cor Dec 26 55 N.R. 32 E.
 443 Road down ravine East of J. L. Stockman's house ascend
 452 Fence E. & W.
 2800 Summit
 3000 bor for 1/2 Dec bet Dec 26 & 27 set angle post at this cor and turn on 1/2 Dec line along ditch fence.
 East 5280 Set 3 mile post 25 N of line

Tuesday Aug 5th 1890

I can not proceed from this point with my team and hence call Jno Harris and Jno Chandler to assist in carrying posts and flagging & continue course.

East

354 Accepted center Dec 26 - set angle post at this point and turn on 1/2 Dec line through center Dec 26
 Ascend

North

1200 Summit - Descend
 1620 Ravine E. Ascend
 1746 Summit Fence E. & W. - Descend
 2700 Cañon N.E. - Ascend
 3100 Summit
 4024 crossing fence N. & S. and E. & W.
 4725 Cañon - N.E.

1450
 5280
 89
 360
 866
 1029
 1157
 1770
 1550
 2700
 2750
 2814
 2930
 3212
 3434

3725
 3776
 4400

field
 Ore