OREGON CC NER RESTORATION FORM Township 5N Section 31 Range 31E County 11-05-2006 Umatilla Date: Condition Report Only Not Found Corner Designation: 5N31E Z4 Remonumented Unrecorded Surveyed In Previous Renewals / Surveys, etc. Referenced Out 08-1865 W.Odell/Lewis STD PARALLEL (110)Only sets 1/4 corners. 12-1874 N. Walden Resurvey (209) Only sets 1/4 corners. 05-1980 W.Kimmel BLM (83-195-B) East - West line indicated only 05-2006 D. Haddock (06-263-C) East - West line indicated only Monument and Accessories Found: (condition and source) No monument set. DIAGRAM R31E ш .46 50 433 S31 S SB S89 *32 'E 360.50ft 2006 PLS 852 5' steel t-post with Umatilla County Survey Monument sign 5/8"dia. x 30" long Iron Rebar with a 1.3"dia. Set 2"dia. Aluminum cap on a 5/8" x 30" long Iron Rebar. 5ft steel T-post Red plastic cap. MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) Set a 2"dia. Aluminum Capped monument (stamped as shown) on a 5/8"OD x 30"long Iron rebar 2" above the ground surface Set a 5' steel T-post with a Umatilla County Survey Marker sign South of the monument . REFERENCES SET: Set two (5/8" dia x 30" long Iron rebar with a 1.3" dia. Red plastic cap) to the bearings and distances from monument shown above in the sketch. Made GPS tie to TRI Stations LAURILA RESET RB 1379 and Oregon State Plane Coord. - North Zone Northing 804547.58 WALLS RB 1396 8589419.36 1112.61 Easting Ortho Height 45 *51'48.48442"N 118 *58'46.53531"W Latitude Longitude Ellipsoidal Height 1043.60 NAD 83 (1991) Location and Comments Compass Declination Surveyors Seal 18 °F Proceed from the junction of HWY 37 and South Cold Springs Highway Southeast on S. Cold Springs Hwy (Umatilla County Rd # 850) approximately 1.56 miles. Thence 100 feet Northeast up the hill to the corner. REGISTERED PROFESSIONAL LAND SURVEYOR

Firm / Agency

RECEIVED BY:

 Haddock Surveying P. O. Box 1574 Pendleton, OR 97801 (541) 276-2174 David L. Haddack

OREGON JULY 12, 1968 DAVID L. HADDOCK 852

RENEWS 6-30-07