

By request of Chas. Allen Oct 12 1905 in T3N R29E W1m

Chains Links

- Commencing at the cor. to Sec 7-8-17 & 18 T3N R29E W1m  
 thence west bet Sec 7 & 18
- 60 00 set Iron pins 1/16 cor
- 88 22 a point 7 Mts South of cor to Sec 7-18-12 & 13  
 thence East on line bet Sec 7 & 18
- 29 85 set Stone for 1/16 cor on N 1/2 of NW 1/4 Sec 18  
 West bet Sec 18 & 19
- 60 00 set Iron pins 1/16 cor
- 87 86 the cor to Sec 18-19-13 & 24  
 thence East on line bet Sec 18 & 19
- 27 76 set post for 1/16 cor on S 1/2 of NW 1/4 Sec 18  
 thence North through Center W 1/2 Sec 18
- 80 32 the 1/16 cor on N 1/2 of NW 1/4 Sec 18  
 thence South on line
- 40 16 set Stone for 1/16 cor in corner W 1/2 Sec 18

John W. Hainbell County Surveyor