

request of S W Phelps Aug 21 1907

J 2 N 16 32 0 W M

Chains Links

Commencing at the $\frac{1}{4}$ sec cor bet sec 3 & 10 1st run
North through center sec 3

50 15 the $\frac{1}{4}$ sec cor bet sec 3 & 34

Hence South on same line

40 07 $\frac{1}{2}$ bet Stone 16+8+5 for center sec 3

60 10 $\frac{3}{4}$ bet Stone 18+10+9 for center $\frac{1}{2}$ sec 3

50 15 the $\frac{1}{4}$ sec cor bet sec 3 & 10

South bet sec 3 & 4

50 57 The Corner of sec 3-4-9 & 10

Hence North on same line

20 14 bet Stone 16+8+7 for $\frac{1}{16}$ corner

40 28 bet Stone 18+7+7 for $\frac{1}{4}$ sec cor

50 57 the cor to sec 3-4-33 & 34

John W. Winchell County Surveyor
assisted by Frank Fowler chairman
Dan Branger "
John Fowler Flagman