

Request of Dick Morrison & Mrs J. F. Adams June 1st 1909

Chains Links

- From the $\frac{1}{4}$ sec corner bet Secs 19 & 20 $\frac{1}{2}$ run
East bet Secs 19 & 20
- 41 20 the corner to Secs 19-20-29 $\frac{1}{2}$ 30
thence west on True line
- 2060 Set Stone 16 x 8 x 3 ft $\frac{1}{16}$ corner
North bet Secs 19 & 20
- 8476 a point 150 lbs East of corner to Secs 17-18-19 & 20
thence $21^{\circ}17'$ E on True line
- 2118 Set Stone in mid of Stone for $\frac{1}{16}$ corner
- 42 36 Set Stone for $\frac{1}{4}$ sec corner
- 63 54 Set Stone in mid of Stone for $\frac{1}{16}$ corner
- 8476 the corner to Secs 19-20-29 $\frac{1}{2}$ 30
North through center of $D \frac{1}{4}$ Sec 19
- 50 88 the center of $B \frac{1}{2}$ Sec 19
thence South on True line
- 25 44 Set Post for center of $D \frac{1}{4}$ Sec 19
East through center of $B \frac{1}{4}$ Sec 20
- 40 12 the $\frac{1}{16}$ corner in center of Sec 20 Set Stone in mound of Stone
West on True line
- 20 06 Set Post in mound of Stone for $\frac{1}{16}$ corner in center of $D \frac{1}{4}$ Sec 20
East bet Secs 20 & 29
- 80 24 the corner to Secs 20-21-28 & 29
thence $\frac{1}{2}$ run West on True line
- 40 12 Set Post in mid of Stone for $\frac{1}{4}$ sec corner bet Secs 20 & 29

John W. Thornhill County Surveyor

Ely Wain and Geo. Wain chainmen Dick Morrison Flagman