



NARRATIVE:

The purpose of this survey was to locate the boundaries of that property for Gifford Hillman. The 1/2" pins we found are not shown on any recorded survey in the County Surveyor's Office, however, ties to the centerline of S.E. 3rd Ave. and centerline of Mill St. as well as the monument at the intersection of S.E. 7th Ave. and Mill St. proved the pins to be in the correct locations.

- denotes set 3/8" x 30" iron pin with aluminum cap stamped PLS 930.
- denotes found 1/2" iron pin
- denotes found 3/8" pin in 3" pipe at intersection of S.E. 7th Ave and Mill St.

	KRUMBEIN ENGINEERING LTD. ENGINEERS - SURVEYORS - PLANNERS 361 S.E. Second Pendleton, Oregon		Scale 1"=30'	Drn. By MLD	Drng. No. 64-14C	Revision 1
	Date 4-2-84	Ckd. By DWA	Job No. 84-1C	Revision 2		
Survey for GIFFORD HILLMAN				5/30/84 LC 84-58-B		
NE 1/4, NW 1/4, Sec. 12, T5N, R35E, N.M.						