



CURVE DATA

No.	Radius	Arc	Chord	Chord Bearing
1	14°00'	182.90	182.42	N83°58'58"E
2	14°00'	217.10	216.62	N83°34'44"E
3	479.26	225.05	222.98	N60°58'32"E

- ⊙ denotes Brass Cap found
- denotes 5/16" iron pin found

NOTE

Bearings and distances are based a survey by the City of Pendleton, dated August 21, 1975, drawing no. 24-7725, and a survey by Krumbain Engineering, Ltd for Gene Roden, dated June 20, 1979, Umatilla County Survey Records drawing no. 9-1211-B.

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Terry E. Hamby
REGON
JULY 14, 1978
TERRY E. HAMBY
1538

RECEIVED BY
Umatilla County Surveyor
Date 4-81
Rec'd by BLS
No. 8-43-8

KRUMBEIN ENGINEERING CO.
ENGINEERS - SURVEYORS - PLANNERS
221 S. Main, Pendleton, Oregon

Drawing for
GENE RODEN
Located in NW 1/4 of Section 5, T2N, R32E, W1M

SCALE
1"=100'
DATE
March 19, 1981
DRN. BY
MA
CKD. BY
TEH
DRNG. NO.
81-14C