

- stake N. 35° E. 40 links from point. Road in lane runs by this point course E. 4 W. I turn thence 30° Left
- N. 71° 40' W. 53.74 Pt. 50 links N. W. of Summit N of Ravine - 8'
- Set angle stake 30 links E. of point, ^{also} Turn thence 55° Right.
- N. 36° 40' W 80.00 Set 3 mile post 45 links East of Pt. I cut A on S. side of post ^{also} Turn 9° 10' Right, along E. side of R. R. track in Vansycle.
- N. 27° 30' W 11.30 Set angle stake 45 links E. of point ^{also} Turn 4° Right
- N. 23° 30' W 17.80 Water Channel in Vansycle Cañon, about E 4 W. at crossing. Precipitous earth bank on N. side of channel + 16'
- 19.70 Over point to old ditch fence E. 4 W.
- 21.90 Water Channel of Vansycle Cañon, N. W at crossing Precipitous Alkali bank on N. side of channel + 15'
- 24.50 Intersect County Road running from N. bndy of Cr. to Geer Springs course S. 60° E. ^{also} N. 60° W. at intersection, I set terminus 45 links N. 44° 30' E. of Pt. against fence on N. side of lane, course as per road intersects

All the posts ^{also} stakes were of the size ^{also} were marked ^{also} mounded as required by law, The road, in general, is well marked; a portion of it, now, already traveled, ^{also} lanes made in fencing. The road appears to be greatly needed as a connection between the different points on Vansycle ^{also} the country East, South & West of same in the vicinity of its location.

I hereby certify that the foregoing notes of the Survey of road no. 313 for Umatilla County, Oregon are correct.

Jno E. Arnold, Co. Survr.

See Plat on page 41.