

N 15-13 W	55.30	S. 7° 43'	" " "	16	
N 22-33 W	62.06	S. 7° 20'	" " "	17	= Leann's barn brass west 183 lks. dist.
N 7-53 W	64.47	R. 14° 40'	" " "	18	
N 10-53 W	66.97	S. 3° 00'	" " "	19	
	73.50				Int. E. + W. fence 508 lks. west of 1/4 Sec. Cor. bet. Secs. 16 + 21.
	80.00				Set 3 m. p. 45 lks. west of line.
N 3-37 E	8.81	R. 14° 30'	Set a. p. MKD. 20		
	13.50				Old road to lower McKay bridge
N 21-55 W	15.43	S. 25° 32'	" " "	21	
	20.50				Ravine, about 10 lks. deep, 75 lks. from bank to bank on line of road, - Descend gully
N 15-55 W	43.40	R. 6° 00'	Set a. p. MKD. 22, J. H. Raley's pump brass E. 47 lks.		
N 46-33 E	52.70	R. 62° 28'	" " "	23	Ascend hill,
N 57-03 E	58.29	R. 10° 30'	" " "	24	
N 60-06 E	71.00	R. 3° 03'	" " "	25	
	80.00				" 4 m. p. 84 links N. of line, against fence on N. side of lane - <sup>note</sup> at this place, the Viewers changed the survey after setting the 4 m. p., which was set 34 links N. of road center, throwing the line of survey at this point 50 lks. south of the first survey, and I leave 4 m. p. unchanged
S 60-20 E	16.17	R. 59° 34'	The 1/4 Sec. Cor. on N. body of N.E. 1/4 of Sec. 16.		
			Set a. p. MKD. 26. on main summit - Descend hill		
N 88-40 E	19.87	S. 31° 00'	" " "	27	
N 58-50 E	22.46	S. 29° 50'	" " "	28	
	28.20				Win fence, course E. + W.
	29.50				plowed furrow E + W. about 5 chs. W. of Sec. Cor.
N 38-05 E	34.47	S. 20° 45'	" " "	29	
N 10-55 W	39.38	S. 49° 00'	" " "	30	
	53.70				Center of S. end of bridge on Tudor Willow Creek. I cut R. 397 on lower brass at S. end of said bridge for terminus of said R. 397. - all posts over of the size and were marked and set in mounds, as required by law.

Shenby certify that the foregoing field notes to road survey 397 for Wasatilla County Oregon are correct.

Jno C. Arnold, Surveyor

Filed July 13 1892  
 W.M. Pierce }  
 Clerk