

## FIELD NOTES OF ROAD NO. 587

COMMENCING at a point 17 rods South of the SE corner of Sec 24 T 4 N R 30 EWM, set stone 22x15x7 ins marked R 587, thence North 54.55 chs Dist  
 thence N 38° W 672 6127  
 thence N 55° E 410 6537  
 N 16° E 485 7022  
 North 978 8000 bet Cottonwood Post 4 ft long 4 ins sq. 18 ins in the  
 ground 30 ft to right marked 1 M  
 thence North 7100 chs dist  
 N 64° W 240 7340  
 N 38° E 500 7840  
 North 160 8000 bet Cottonwood post 4 ft long 4 ins sq 18 ins in the  
 ground 30 ft to right marked 2 M, thence North 8000 bet Tamarack post  
 4 ft long 4 ins sq 18 ins in the ground 30 ft to right marked 3 M R T  
 587 dug pits and raised mound of earth alongside

I hereby certify that the foregoing Field notes of Road No 587 are correct  
 as surveyed by me on the 7th day of June 1906.

John W Kimbrell  
 County Surveyor for Umatilla County, Oregon

## REPORT OF BOARD OF COUNTY ROAD VIEWERS

In the Matter of Viewing, Surveying and Laying Out County Road No 587  
 To the Honorable County Court of the State of Oregon for Umatilla County.  
 We, the undersigned Board of County Road Viewers heretofore instructed to  
 view, survey, and locate Road No 587 submit the following report;  
 Pursuant to an order of the Honorable County Court we met at County  
 Surveyors Office in Pendleton Oregon on the 7th day of June 1906  
 We called to our aid

J M Carter, Chairman  
 S B Elder, Chairman  
 L C Rothrock, Flagman  
 J W Kimbrell, Marker

who were by the Surveyor each duly sworn. We viewed, surveyed and located said  
 Road No 587 as specified in our order. We find said route practicable for the  
 1st 3 miles and would most respectfully recommend the same be declared and  
 established as a public highway of Umatilla County Oregon, the cost of  
 construction and opening the road to public travel would be about \$175°. The  
 damage to property owners along the route to-wit J M Elder, Walter Bitney  
 W J Furnish, Mrs W T Boyington \_\_\_\_\_ Thomas and \_\_\_\_\_ Richardson would be  
 nothing.

John W Kimrell  
 J M Ferguson  
 L C Rothrock

Board of County Road Viewers of Umatilla County, State of  
 Oregon.

Filed July 7, 1906  
 Frank Saling, Clerk  
 By- R T Brown, Deputy  
 Approved July 13, 1906  
 T P Gilliland, County Judge  
 Horace Walker, County Comm.  
 H B Lee, County Comm.

## FIELD NOTES OF ROAD NO. 588

COMMENCING at a point 80 rods East and 96 rods and 25 feet South of the  
 NE corner of the SE1/4 of Sec 25 in T 5 N R 30 EWM.  
 bet fir post 4 ft long 4 ins S of, 18 ins in the ground 30 feet West of Initial  
 point marked R 588 dug pits E & W and raised mound of earth alongside, thence  
 S 33° W 44 5 chs dist  
 thence S 1° 30' E 490 937  
 S 23° E 527 1462  
 South 2000 3462 gulch Fill 5 ft deep 50' wide  
 2300 5762  
 S 57° 155 5917  
 S21° 341 6258  
 South 1742 8000 set Tamarack post 4 ft long 4 ins sq 18 ins in the  
 ground 30 ft to the right marked 1 M dug pits and raised mound of earth  
 alongside thence S 7° 30' W 1908 chs dist  
 South 1764 3672  
 S 38° W 255 3927  
 S 59° E 174 4101  
 South 3304 7403  
 S 15° W 595 8000 set Cottonwood Post 4 ft long 4 ins in the  
 ground 30 ft to the right marked 2 M dug pits and raised mound of earth  
 alongside thence S 15° W 588 chs dist  
 S 12° E 370 958  
 S 59° W 134 1092  
 S31°E 490 1582  
 thence South 530 2112  
 West 1040 3152  
 S 71° W 1075 4227  
 South 160 4387 R T set post 4 ft long 4 ins sq 18 ins in the  
 ground marked R T 588 dug pits and raised mound of earth alongside.

I hereby certify that the foregoing Field Notes of Road No 588 are correct  
 as surveyed by me on the 8th day of June 1906.

John W Kimbrell  
 County Surveyor of Umatilla County, Oregon.