


Fnd. 2 3/8" Brass Cap  
 Set in 1982 by Krumbeln  
 in place of crank of cut  
 with

**NARRATIVE:**

The purpose of this survey is to correct the outside boundaries of parcels surveyed by me using incorrect G.L.O. corners at the N 1/4 and NE corner of Section 26. I set new monuments at those locations in my Area 1-1987 County Remonumentation Survey. The following surveys are being changed:  
 My 1980 Survey for Lee Baggett Co. # R-140-B,  
 My 1986 Survey for Jubadah Miller Co. # 86-070-A,  
 My 1987 Survey for Ron McCoy Co. # 87-033-A,  
 and one corner on My 1987 Survey for Lee Baggett Co. # 87-034-A.  
 To avoid confusion on which monument is correct I set 1/4" I.D. Iron pipes at the corrected corners with washers (#951) cemented to them.  
 In all of those surveys, which were proposed partitions, the County Planning Department required that 10 additional feet be given for more road right-of-way, But I don't think any got deeded to the county.

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR  
*G. Dennis Edwards*  
 OREGON  
 QUAL. REG. NO.  
 G. DENNIS EDWARDS  
 951



**LEGEND:**

- Fnd. 2 3/8" Brass Caps. See My Area 1-1987 Remonumentation Survey for Umatilla County.
- Set 2 3/8" Brass Caps on 1" x 30" Iron pipes 4" below surface at C 1/4.
- Fnd. rebar, size as noted, set in 1980, 1986 or 1987. See my narrative.
- ◎ Set 1/4" I.D. x 30" Iron pipes with washers, stamped 951, cemented to the top.
- Set 1/2" x 24" rebar with plastic cap #951.

RECEIVED BY  
 Umatilla County Surveyor  
 Date: 1/2/92  
 Initials: [Signature]

Survey for G. DENNIS EDWARDS  
 in Sec. 26, T5N, R28E, W.M.  
 Umatilla County, Oregon  
 2/25/92 Job # S9201001-A  
 Edwards Surveying P.O. Box 763  
 567-3336 Hermiston, Oregon 97838