

Record of Corner Monumentation

K-14

History of original corner establishment:

NW 1/16 corner Section 14, was monumented by C.E. Redfield during his 1919 circa. He set a 2 1/2" brass cap on a 36" pipe in a plowed field.

Description of corner evidence found:

I found no trace of this monument as it is located in a field that has been farmed for many years. No doubt the monument has been destroyed during farming operations.


Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 2 1/2" Aluminum Cap on a 36" pipe and being stamped as shown in the diagram. I buried the pipe 32" in the ground and placed a steel fence post alongside to aid in locating the monument in the future.

Diagram:

NW 1/16
S 14
T 1 N R 33 E
2003
ORLS 645

REGISTERED
PROFESSIONAL
LAND SURVEYOR



02-20-03

OREGON
JULY 10, 1964
JAMES H. HAMBLETON
645

03-35-B