

USDA-FOREST SERVICE

Index
File No. Z-13
T LN R. 37E
Merid. WILL


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

R.D. WALLA WALLA County UMATILLA
N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

ORIGINAL POST IS GONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIGINAL 30" FIR IS DOWN. SCRIBES "BL TIN R37E 534 BT" ARE VISIBLE. THIS LOG SLID DOWN HILL ABOUT 15' FEET WHEN IT FELL. ROOTS BEAR N10°E, 12.5 FT. ORIG. 18" FIR IS A DECAYED STUMP N40°W, 6.6 FT. NO MARKS REMAIN. ORIG. 24" FIR IS DOWN. SCRIBES "BL TIS R37E 54 BT" ARE VISIBLE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

THIS TREE SLID DOWN HILL ABOUT 20' WHEN IT FELL. ROOTS BEAR S15°E, 50.2 FT. I PLACED A LOCATION POSTER ON A 12" FIR S60°W, 18 FT. FROM CORNER. CORNER IS ABOUT 500' EAST OF ROAD 3116-021.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature Dennis L. Gaylord Title PLS 1636 Division S.O. Headquarters 7-17-86 Date 7-17-86 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13