

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 10/30/01**

**CORNER DESIGNATION: 2N32, A-3.** The North 1/4 Corner of Section 6.

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

Most current is Umatilla County Surveyor's Corner Record No. 88-19-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap 6" above ground level in circular mound of stone in good condition, marked as shown in monument marking detail.  
As per corner certificate, accessories are O.K., except that both bearing object signs are missing.  
Corner has only 2 accessories.

**MONUMENT MARKING DETAIL:**

T3N R32E

1/4 S31

S6

T2N R32E

1988

PLS 1106

**LOCATION & COMMENTS:**

Located in fenced area on small hill between two small draws.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 741553.09

E = 8621356.33

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N32A3

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON 02  
JULY 22, 1977  
WILLIAM R. WELLS  
1106 01

*renews 6-30-02*

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By RP

No. 01-210-9

05  
26  
05

*Fawn A. Norman*