

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 11/28/01

CORNER DESIGNATION: 2N32A7, The North Quarter Corner of Section 5.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors Corner Record: 88-19-C.

MONUMENT AND ACCESSORIES FOUND:

Found a PK nail with white aerial premark "T" painted through it (four other PK nails for straddle ties also found). This PK nail fits the position of the 1 3/4" brass disk reported on corner record. P.K. nail is believed to have been established by City of Pendleton, with reference to the brass disk monument. Accessories indicated on corner record are destroyed by expansion of the Airport parking area.

MONUMENT MARKING DETAIL:

LOCATION & COMMENTS:

Located in paved airport parking area on North side of first turn entrance into parking area.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 741670.00

E = 8626625.36

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N32A7

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

05

05
26
05

From R. Neuman

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Rec'd By XX

No. 02-479