

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 02/04/02

CORNER DESIGNATION: 2N32L5, The East Quarter Corner of Section 18.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most recent Umatilla County Surveyors Corner Record: 92-92-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap with top 20" below ground, marked as shown in monument marking detail. This corner has no accessories.

MONUMENT MARKING DETAIL:

T2N R32E
1/4
S18 | S17
1992
PLS 1106

LOCATION & COMMENTS:

Corner located approximately 50 feet North of the centerline of a small swale in a CRP field.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 728363.36
E = 8624310.88

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N32L5

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106 02

renews 6-30-02

05

05

26

05

Karen Q. Neuman

RECEIVED BY

Umatilla County Surveyors

Date 2-02

Rec'd By KK

02-439