

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 12/31/01**

**CORNER DESIGNATION: 2N32, V-23, The North 1/4 Corner of Section 36.**

**PREVIOUS RENEWALS/ SURVEYS, ETC..:**

Corner was reestablished under Umatilla County Surveyor's Corner Record No. 94-109-C and accompanying Record of Survey.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap monument on galvanized iron pipe, buried 14" below ground in farmed field. Corner marked as shown in monument marking detail. As per Corner Record, accessories are intact. Corner has four accessories.

**MONUMENT MARKING DETAIL:**

T2N R32E  
S25  
1/4 -----  
S36  
1994  
PLS 1106

**LOCATION & COMMENTS:**

Corner located in an active farmed field.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 715661.08  
E = 8648388.29

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N32V23

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

**RECEIVED BY**

Umatilla County Surveyor

Date 2-02

Rec'd By JK

No. 02-46-9