

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 11/29/01

CORNER DESIGNATION: 2N32X13, The East Quarter Corner of Section 33.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors Corner Record: 94-109-C.

MONUMENT AND ACCESSORIES FOUND:

Found 2 1/2" brass cap on galvanized iron pipe monument set flush with ground in small mound of stones, in fence running North-South, marked as shown in monument marking detail.

Per corner record, all accessories are intact except bearing object tag is missing from the accessory located at Southwest accessory.

MONUMENT MARKING DETAIL:

T2N R32E
1/4
S33 | S34
1994
PLS 1106

LOCATION & COMMENTS:

Go North to end of Appaloosa Lane. Corner is in North-South fence which is on West side of house on West side of Road, approximately 100' North of house.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 712780.67
E = 8635236.54

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N32X13

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY
Umatilla County Survey
Date 2-02
Exp. XX
No. 112-4349