

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 02/20/02

CORNER DESIGNATION: 2N33N9, The Northeast corner of Section 20.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most recent Umatilla County Surveyors recorded corner record: 97-222-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap 6" below gravel road.

Monument marked as shown in monument marking detail.

As per corner accessories are intact except the steel fence post with witness sign attached in Northwest quadrant is broken and laying on ground.

MONUMENT MARKING DETAIL:

T2N R33E

S17 | S16

S20 | S21

1997

PLS 1106

LOCATION & COMMENTS: Corner is located in Billy Road, County Road No. 1043.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 726679.17

E = 8661159.62

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33N9

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6/30/02

RECEIVED BY

Umatilla County Surveyor

Date 5-02

Rec'd By KK

No. 02-116-9