

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 02/20/02

CORNER DESIGNATION: 2N33R13, The Northeast Corner of Section 28.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most recent Umatilla County Surveyors recorded corner record: 97-222-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap 3" below paved road.
Monument marked as shown in monument marking detail.
As per corner record, accessories are intact.

MONUMENT MARKING DETAIL:

T2N R33E
S21 | S22
S28 | S27
1997
PLS 1106

LOCATION & COMMENTS: Corner is located in South Market Road at 4-way road intersection.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 721401.74
E = 8666578.36

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33R13

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6/30/02

RECEIVED BY
Umatilla County Survey
Date 5-02
Rec'd By JK
No. 02-121-9