

Index

File No. V-23

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

T 2N R. 36E

R.D. Walla Walla

County Umatilla


Merid. Willamette

N.F. Umatilla

State Oregon

CORNER DIAGRAM Sec. 36

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 2

Orig. 6" Fir now down and mostly rotted Fir S10E-15.2 ft. reverse scribing visible.

Orig. 7" now down and mostly rotted Pine N85E-26.4 ft. scribing visible.

PHOTO IDENTIFICATION DATA

Photo No. 1280-49

Filed At. Umatilla N.F.

Object Ident. two I.P.'s

Ident. By L. D. Boring
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 3

From tis intersection with Rd. #3128 just East of a cabin near the SW 1/16 of Section 36 follow logging road Northerly to creek and East along creek to just past where road crosses main creek. Go North to posted line and East to corner.

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

Larry D. Boring

Land Surveyor

6/83 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" Aluminum pipe with a 2½" Aluminum cap solidly driven between two roots of Northwest BT 25" into ground.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

26" Wh.Fir N54W-2.6 ft. scribed ¼S25BT and with a 1" Brass disk stamped PLS 896.
11" Wh.Fir S21W-9.8 ft. scribed ¼S36BT and with a 1" Brass disk stamped PLS 896.

Work Done By Larry D. Bishop Title Surveyor Date 6/83 State Registration No 896
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Set guard post East with signs 54-2 and 54-4.
Nailed BT and 54-4 signs to BT's and painted band and blazes red.

Index File No. V-23

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____


T ZN R. 36E

R.D. WALLA WALLA County UMATILLA

Merid. WILL.

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE - ORIGINAL POST IS GONE - A POST OF RECENT ORIGIN IS 25' WEST OF CORNER POSITION.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIG. 7" PINE IS DOWN & DELAYED - SCRIBING & REVERSE VISIBLE. BEARS N85°E, 26 1/2 FT.

ORIG 6" FIR IS DOWN & BADLY DECAYED - REVERSE SCRIBES VISIBLE ON A PIECE OF OVERGROWTH WOOD LYING ON GROUND. BEARS S10°E, 15 1/2 FT.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

I PLACED A K TAG ON A 14" FIR N62°E, 15 FT FROM CORNER.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature Dennis L. Gaylord Title PLS Division 1636 Headquarters _____ Date 7-14-82 7100-52 (3. 68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.