

BW-11

Index File No. Z-9

CORNER RECORD (SEARCH)


Tract or Survey No. \_\_\_\_\_

Cor. No. Z-97

T. 25 R. 33E  
Merid. Will.

R.D. Ukiah County Umatilla  
N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

26" DBH Fir BT - Green + Standing - Closed Face -  
Chopping revealed scribing. Tree bears N. 65° W.,  
100 lks. distant from corner.

PHOTO IDENTIFICATION DATA

Photo No. EQO, 8-105(9-3-66)  
Filed At. \_\_\_\_\_  
Object Ident. BT  
Ident. By Tom SUPERLAND  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

old remains of a fence about 20' W. from  
approx. location of corner Stones may have been  
used in building fence.

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

Signature: Ken Magoon

Title Eng. Aide Division USFS Headquarters Umatilla - S.O. Date 8-6-69  
7100-52  
REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Placed BT sign (54-3) and attention sign (54-4) on BT.

Painted BT red.

Placed location poster (458) at bottom of S. canyon 2.5 ch. W of corner.

Work Done By Mike Lilly Title Eng'r Aide Date \_\_\_\_\_ State Registration No. or Agency U.S. FOREST SERVICE

Certified Cor. Record Prepared? Yes  No \_\_\_\_\_ Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Run W. Compass line from N<sup>1</sup>/<sub>4</sub> cor. of sec. 2, T3S, R33E, to area of corner as described in GLO-notes.

Index File No. Z-9 T. 2S R. 33E M. Will. Tract or Surv. No. \_\_\_\_\_ Cor. Z-9