

Index  
File No. \_\_\_\_\_

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. U.I.R

Cor.  
No. 6 1/2 M.P.

T 2 S. R. 34 E.

R.D. \_\_\_\_\_ County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



*U.I.R*  
*6 1/2 M*

DESCRIBE CORNER MONUMENT FOUND

2 1/2" DIAM. BRASS CAP SET ON A 2" QD IRON  
PIPE EXTENDING 11" OUT OF ROCK MOUND,  
CAP MKD. PER SKETCH.

T 2 S R 34 E

*U.I.R*  
*6 1/2 M*

1917

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

24" D.B.H. (18") X 6' HIGH PONDEROSA PINE STUB, N. 25° W., 141 LKS,  
W/SCRIBES VISIBLE ON OPEN FACE.

23" D.B.H. (14") PONDEROSA PINE, N. 40° 15' E., 123 LKS, W/BOTH FACES  
HEALED.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

TAKE ROAD 21 TO WEST LINE OF S. 31, T. 2 S., R. 35 E., TAKE  
ROAD NORTH TO 1/4 S. 25  
S. 35 (1.2 ± MI) GO NORTHWEST ALONG ROAD ON  
RIDGE TO FOREST BOUNDARY, FOLLOW POSTED BOUNDARY N. 20° E,  
800' ± TO MILE POST IN CLEARING.

Signature

*Clayton J. Mansel*

Title

LAND SURVEYOR

Division

Headquarters

Date

7-11-85

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

RAISED STONE MOUND.

SET STEEL POSTS 3'x N. 5'S. W/ATTN, MON. AND PROP. BNDRY. SIGNS ATTACHED.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

13" D.B.H. DOUGLAS FIR, N. 5° W., 109.0', SCRIBED 6 1/2" MUIR BT. SET A BRASS WASHER MKD. RPLS 1910 BTWN. B & T.

ALL BT'S. HAVE B.T. TAGS, ATTN. SIGNS, AND BANDS AND FACES PAINTED RED.

Work Done By G.J. MARTIN Title LAND SURVEYOR Date 7-11-85 State Registration No. LS 1910  
or Agency

Certified Cor. Record Prepared? Yes (No) Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. T. 2 S R. 34 E M. WILLAMETTE Tract or Surv. No.

Cor. U18  
6/1/82

Index

File No. \_\_\_\_\_

T 25 R. 34E

Merid. Will

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. UIR


Cor.

No. MP 61½

R.D. Ukiah County Umatilla

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found brass-capped iron post, 2" dia., loose in the ground, 20" above surface.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Orig. 14" pine is alive with double, healed blazes, and bears N40°15'E, 81.2 ft from corner.

Orig. 18" pine is snag broken off 5' high with scribes visible on upper blaze and lower blaze is healed. Bears N25°W, 93 ft from corner

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

Signature

Title

Division

Headquarters

Date

7100-52-(3,68)

*Dennis L. Layford*

*PLS 1636*

*5-24-84*

**CORNER RECORD (PERPETUATION)**

**MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

**ACCESSORIES : DESCRIBE NEW, BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

**REMARKS**

Index File No. T. R. M. Tract or Surv. No. Cor.