

USDA-FOREST SERVICE

Index

File No. N-3

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 2S R. 35E R.D. Ukiah County Umatilla

Merid. W.M. N.F. Umatilla State Or.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor. falls on NE slope W of draw in second growth and fallen Lodgepole. From 023 rd. go W along posted property line approx. 700'.

Signature

F. J. Munro

Title

L.S.

Division

Headquarters

Date

9/26/84

7100-52 (3-68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2½"x30" alum. pipe with 3" alum. cap mkd:

T2S R35E

¼ $\frac{S18}{S19}$

PLS 1832

1984

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

D. fir, 10", N17½°W, 24.2 ft.

D. fir. 11", S73°E, 22.4 ft.

BTs have reqd. paint, tags & signs.

10

Work Done By F. S. Munro Title L. S. Date 9/5/84 State Registration No. 1832
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Umatilla Co. Surveyor Date _____

11

REMARKS

12

Index File No. N-3 T. 2S R. 35E M. W.M. Tract or Surv. No. _____ Cor. _____

13

USDA-FOREST SERVICE

Index
File No. N-3

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

T 28 R. 35E R.D. Ukiah County Umatilla

Merid. W.M. N.F. Umatilla State Or.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor. falls on NE slope W of draw in second growth and fallen Lodgepole. From 023 rd. go W along posted property line approx. 700'.

Signature

F. J. Munro

Title

L.S.

Division

Headquarters

Date

9/26/84

7100-52-(3,68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/8" x 30" alum. pipe with 3" alum. cap mkd:

T2S R35E

1/4 S18
S19

PLS 1832
1984

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

D. fir, 10", N17 1/2° W, 24.2 ft.
D. fir, 11", S73° E, 22.4 ft.

BTs have reqd. paint, tags & signs.

Work Done By F.S. Munro Title L.S. Date 9/5/84 State Registration No. 1832
or Agency

Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co. Surveyor Date

REMARKS

Index File No. N-3 T. 2S R. 35E M. W.M. Tract or Surv. No. Cor. 13