


LAND CORNER RECORD

1. T 3N R 37E No. E 9 Cor. Sec. 4 Mer. Will State Oregon (Rectangular) N. F. Umatilla Dist. Pendleton 10

2. Corner Status



3. Original-Description Resurvey Vol. 192 Page 26 Where Recorded GLO year 1879

4. Description of Corners: Resurvey set Basalt stone 11x12x4 and post in mound of stone on steep south face of bluff for corner to section 4,5,8 & 9.

5. Investigation Notes: Found old stick in pile of stone in poor condition. Stick size 6"x1". No markings.

Below sub. pt. S 10° W there are 3 layers of rock bluffs. The corner is approx. 20' from the base of the last bluff; painted with silver paint. The stick is beneath the silver painted rock.

A fence running N.W. and S.E. is on west side corner approx. 150 ft. dist.

I placed a K tag on 15" P P sub. pt. to help in the location of this spot.

Best way in would be by use of photo.

7. Photo Identification

Photo No. UM 32B -5  
Ident. By: \_\_\_\_\_

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
Field Book No. \_\_\_\_\_  
Where Filed \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_  
Needs Verif. X Monument NO  
Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_  
Land Status \_\_\_\_\_

6. Signed A. Galbraith Title Range Tech. Date 5-12-64

*[Handwritten signature]*

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By \_\_\_\_\_ Title \_\_\_\_\_

License \_\_\_\_\_ Agency \_\_\_\_\_ Date \_\_\_\_\_

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_  
(Agency)

(Date) (City) (County) (State)

14. Remarks:

E-9