

LAND CORNER RECORD

LL 5680;2

(Rectangular)

1. T 3N R 37E No. T 5 Cor. 1/4 Mer. Will State Oregon N. F. Imatilla Dist. Pendleton 20

2. Corner Status

3. Original Description Resurvey Vol. 192 Page 2 Where Recorded G.L.O. year 1879

4. Description of Corners: Resurvey found original fir tree and two witness trees. 1879

7. Photo Identification
 Photo No. _____
 Ident. By: _____

5. Investigation Notes:

Searched for, but no evidence of 1/4 cor.

Found what might be a bearing tree, 12" fir.
 9" fir had the remains of a corner off of a K tag. We tied two stripes of orange ribbon on tree that had a piece of the K tag on it.

8. Plane Coordinate Position Data
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filed _____

9. Evaluation
 Authentic _____
 Needs Verif. X Monument NO
 Re-estab. _____ Survey _____
 Land Status _____

6. Signed A. Galbraith Title Range Tech. Date 5-5-64 st

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
(Agency)

(Date) (City) (County) (State)

14. Remarks:

L-5