

USDA-FOREST SERVICE

Index File No. J-1

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. _____


T 3N R. 38E

R.D. WALLA WALLA County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE - MAY HAVE ROLLED DOWN STEEP HILLSIDE. ACCESSORIES FOR SUPERCEDED CORNER SET IN 1899 WERE RECOVERED. OLD CORNER BEARS N 0° 54' E, 291.72 FEET

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

OLD CORNER ACCESSORIES: ORIGINAL 30" PINE IS A 36" PONDEROSA PINE WITH DOUBLE HEALED BLAZES. BEARS S 23° 30' E, 114.84 FEET. ORIGINAL 25" FIR IS NOW A 36" DOUGLAS-FIR SNAG 35 FEET HIGH WITH DOUBLE HEALED BLAZES. BEARS N 18° 30' E, 19.14 FEET.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

I PUT BT SIGNS ON BOTH TREES. OLD CLOSING CORNER IS JUST NORTH OF TOP OF A SMALL SPUR RIDGE. THE PINE BT IS SOUTH OF THE TOP OF THE SPUR RIDGE.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature Dennis T. Layford Title _____ Division PLS Headquarters 1636 Date 9/18/1997 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. _____