

USDA-FOREST SERVICE


Index File No. J-25
 T 35 R. 31E
 Merid. WILLI

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____
 R.D. UKIAH County UMATILLA
 N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE - 18x10x6" - LYING ON SIDE & BROKEN.
 NO MARKS VISIBLE,

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIG. 30" LARCH IS NOW A SAWN STUMP, I OPEN & FIND SCRIBING & REVERSE, "BT" BEARS S45°W, 66.66 FT. ORIG. 10" FIR, NOW A 7 FT. HIGH SNAG 18" DIAM. W/ HEALED BLAZES BEARS N40°W, 56.76 FT. ORIG. B.T. TO N.E. IS A BADLY DELAYED STUMP. ORIG. SE BT IS GONE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3 FT EAST OF N-S FENCE AT BASE OF WEST SLOPE.
 PLACED B.T. SIGNS ON NW & SW B.T.'S.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

Dennis S. Layland

PLS 1636

11-4-80

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.