

USDA-FOREST SERVICE


Index
File No. L-25
T 3S R. 31E
Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ukiah County Umatilla Tract or Survey No. Sec 13 Cor. No. E 1/4
N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 14" dia Tamarack bears N50°W 4.62 ft dist (old BT) fallen. Visable scribing "S BT".

PHOTO IDENTIFICATION DATA

Photo No. 616140 780-8
Filed At. Umatilla Nat. Forest
Object Ident. Trees
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Road #5415 to road #050, then North on #050 approximately 1.5 miles to fork, then West on left fork across ridge top North of bridge creek, turning North with road approximately 1/4 mile to switch back rack, then North 100 ft to E-W fence, then West along fence 300 ft to fence intersection N-S and E by CC then North 2,000 ft over steep North slope along fence, then East 75 ft to corner on timbered slope.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Willie R. Wells

Title

PLS 1106

Division

Headquarters

Date

October 18, 1982

7100-52-(3-68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" brass cap on 2 1/2" x 30" l. pipe 20" in the ground with mound of stone.
 Set steel fence post with 54-4 sign attached North of corner. Cap marked:

T3S
 R31E R32E
 1/4S13
 1982
 PLS 1106

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 12" W. Fir bears N19°W 30.0 ft dist marked: 1/4 S13 BT.
 A 9" W. Fir bears S8°W 43.4 ft dist marked: 1/4 S13 BT.
 Blaze faces and 6" red band around bearing trees painted red. Trees tagged with 54-3 and 4 signs.
 New BTs have lower blaze, scribed BT, with brass washer stamped PLS 1106 nailed flush.

Work Done By W. R. Wells Title Surveyor Date 10/18/82 State Registration No. PLS 1106
 or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Umatilla County Surveyor Office Date _____

REMARKS

Witnessed by: Leslie E. Wilson

USDA-FOREST SERVICE


Index
File No. L-25
T 35 R. 31E
Merid. WILL

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____
R.D. UKIAH County UMATILLA
N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIG. 10", Now 14", LARCH IS DOWN, HAS SCRIBING VISIBLE ON A NEARLY HEALED BLAZE, BEARS N58W, 4.62 ft. FRAGMENTS OF PINE W/ SCRIBING VISIBLE WERE FOUND LYING IN GENERAL VICINITY OF ORIG. S.E. B.T.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

THIS CORNER IS 60 FT. EAST OF N-S FENCE LINE.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

7100-52-(3.68)

Dennis L. Gaylord

PLS 1636

11-4-80

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.