

USDA-FOREST SERVICE

Index

File No. T-25

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. Sec 25 Cor. No. E 1/4


T 3S R. 31E

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

3" brass cap on 2 1/2" l. pipe 3" out of ground.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 8" dia Spruce brs S37¹/₂°W 35.1 ft dist tagg N37¹/₂°E53lk dist-recent BT
 A 19" dia W.Fir brs West 18.7 ft dist tagg E28 lk dist (old BT) healed blaze.
 A 10" dia Lodgepole Pine Sng .brs E5.2 ft dist tagg W5.2 ft dist (old BT)
 Visible scribing.

PHOTO IDENTIFICATION DATA

Photo No. 616140 780-6
 Filed At. Umatilla Nat. Forest
 Object Ident. Trees
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Yellow Jacket Road to road #5415, East to 200 ft past 2nd cattleguard then South on jeep road 3/8 mile and West 50 ft to corner in East edge of timber in small clearing.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

Signature William R. Wells

Title PLS 1106 Division _____ Headquarters _____ Date September 29, 1982

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set steel fence post with 54-2 and 4 signs, 5 ft North of corner.
Cap is standard BLM. Cap marked:

T3S
R31E | R32E
1/4 S25
1978

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Blaze faces and 6" band around bearing trees were painted red. Tagged trees with 54-3 and 4 signs where needed.

Work Done By W.R. Wells Title Surveyor Date 9/29/82 State Registration No. PLS 1106
or Agency

Certified Cor. Record Prepared? Yes No Filed At: Umatilla County Surveyor Office Date

REMARKS

Witnessed by: Leslie E. Wilson

Index File No.
T-25

T. 3S

R. 31E

M. W&M.

Tract or Surv. No.

Sec 25

Cor.

E 1/4


Index
File No. T-25

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

T 3 S R. 31 E R.D. Ukiah County Umatilla
Merid. Willamette N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Material: None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

North-South fence but no corner (it was a post). A 10-inch lodgepole pine snag bears east from fence approx. 18 feet scribed 1/4 S. B.T. It has a Georgia-Pacific location poster which explains that although the tree is in T3S., R.32E., Sec. 29, that it is B.T. for T3S., R.31E., Sec. 25. A 16-inch white fir bears west from fence approx. 6 feet. It has closed blazes. It also has a Georgia-Pacific location poster declaring it to be the 1/4 corner B.T. for

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
(cont'd on back)

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature
Tom Holman

Title
Eng. Tech.

Division

Headquarters

Date
11/17/75

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed a blank B.T. tag on each B.T.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

(cont'd from 3)

REMARKS

Sec. 25, T3S., R.31E. These trees fit original GLO notes. However, their locations indicate that the fence is about 12 feet west of line. If so, Forest Service cutting was in trespass.